



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 54

Defect Details

During heaving up of Recue boat to secure on board limit switch activating even the rescue boat still above the water level due to excessive old grease with dusk on the limit switch weight.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Safety

Applicable Dates

Date Raised : 21-Mar-2021

Date Completed : 21-Mar-2021

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	03/Jun/2021
Potential to become a serious accident : Medium			Recurrence : Low		

Causes

Excessive old grease with dusk on limit switch weight.

Corrective Action

Cleaned the limit swith weight and removed the old and dirty grease.

Preventive Action

Proper maintenance and inspection. Following PMS procedure

Applicable Tags**Follow Up**

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------