



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 81

Defect Details

During the arrival of the pilot to assist the ship's navigation on the river, a member of the port security team tried to climb on board using the pilot's ladder. The duty officer of our vessel observed this, and he was stopped immediately, not being allowed, taking into account that he did not have the necessary training and the necessary equipment.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Supervision / Leadership / Planning	Office Dept :	Safety

Applicable Dates

Date Raised : 22-Jul-2023

Date Completed : 22-Jul-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : High			Recurrence : Medium		

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Inadequate Communication

Direct Causes- Unsafe Acts			
Instructions / Orders not Followed			
Job Factors			
Inadequate Familiarization			
Personal Factors			
Inadequate Experience			
Follow Up			
On	By	Follow Up	
Before & After Pictures			
Before		After	