



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 101

Defect Details

During the daily patrol was observed that on boiler no 2 second sight glass a steam leakages.Immediately all safety precautions have been carried out ,in order to eliminate the leakages.When was dismantled , on the both ends of the sight glass was observed that gaskets are made from ordinary material .Both gaskets have been replaced with a new ones fabricated on board with a better quality.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Technical

Applicable Dates

Date Raised : 22-Nov-2023

Date Completed : 22-Nov-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : High			Recurrence : Medium		

Causes

Gaskets material was poor and not a special material for steam

Corrective Action

Gaskets have been changed with new ones fabricated on board ,with a good quality

Preventive Action

Daily routines to be done , vessel staff to pay attention to all the details

CONTRIBUTING FACTORS

Follow Up


On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------




Notification

 File Not Uploaded




Notification

 File Not Uploaded




Notification

 File Not Uploaded



Notification

 File Not Uploaded