

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 129

Defect Details

While preparing the accomodation ladder Officer noticed that one A.B. was ready to come out at ship's gangway without wearing lifejacket.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Improper PPE	Office Dept:	Crew			

Applicable Dates

Date Raised: 23-May-2021 Date Completed: 23-May-2021

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Francis Timothy Monteiro
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	03/Jun/2021
5	<u> </u>			,	

Potential to become a serious accident: Low Recurrence: Low

Causes

Inadequate practice

Corrective Action

The Ch. Officer immediately stopped the A.B. from his action and ordered him to wear a lifejacket and after proceed for ladder preparation.

Preventive Action

The crew must be reminded of safety procedures and safety working practice according the company safety manual.

Applicable Tags

Descriptions

Others

Root Causes- Job Factor

Inadequate Work Standards

Near Miss Details Printed On: 09-Jun-2021 1/2

Root Causes- Management Factors Others **Root Causes- Personal Factor** Lack of Skill **Direct Causes- Unsafe Conditions** Others **Direct Causes- Unsafe Acts** Failure to Follow Rules and Regulations **Job Factors** Inadequate Work Standards **Personal Factors** Inadequate Experience Follow Up On **Follow Up** Ву **Before & After Pictures Before** After