



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 78

Defect Details

During un-mooring operation at Georgetown Guyana was noticed one O/S standing between the lines. Chief Officer reminded O/S the safe working practices and later briefed him.
To be discussed during the forthcoming Safety Meeting.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Capabilities	Office Dept :	Safety

Applicable Dates

Date Raised : 23-May-2023

Date Completed : 24-May-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Low		

Causes

Corrective Action

Preventive Action

Applicable Tags

Descriptions

Fatality

Injury

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision			
Root Causes- Personal Factor			
Improper Motivation			
Lack of Skill			
Direct Causes- Unsafe Acts			
Instructions / Orders not Followed			
Job Factors			
Inadequate Supervision			
Inadequate Work Standards			
Personal Factors			
Lack of Skill			
Follow Up			
On	By	Follow Up	
Before & After Pictures			
Before		After	