



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 141

### Defect Details

AN A.B. TRIED TO REPLACE A CHIPPING GUN WITHOUT ISOLATING THE AIR SUPPLY

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Office Dept :	Safety

### Applicable Dates

Date Raised : 24-Apr-2023

Date Completed : 26-Apr-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	26/Apr/2023
Potential to become a serious accident : Low			Recurrence : Low		

### Causes

LACK OF SAFE PRACTICE

### Corrective Action

CORRECTED ON THE SPOT BY OOW AND BRIEFED AS PER SMS AND CSWP.

### Preventive Action

EMPHASIS ON SAFE WORK PRACTICE TO BE RE-ORIENTATED AT EACH JOB TO BE CARRIED OUT

### Applicable Tags

#### Root Causes- Personal Factor

Lack of Knowledge

#### Substandard Acts

Failure to observe basic safety rules

### Follow Up

On	By	Follow Up	
26/Apr/2023	Nawin Khaware	Agree with preventive measures, Remain observant & ensure regular compliance with same.	

**Before & After Pictures**

Before	After
--------	-------