



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 141

Defect Details

AN A.B. TRIED TO REPLACE A CHIPPING GUN WITHOUT ISOLATING THE AIR SUPPLY

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Office Dept :	Safety

Applicable Dates

Date Raised : 24-Apr-2023

Date Completed : 26-Apr-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	26/Apr/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

LACK OF SAFE PRACTICE

Corrective Action

CORRECTED ON THE SPOT BY OOW AND BRIEFED AS PER SMS AND CSWP.

Preventive Action

EMPHASIS ON SAFE WORK PRACTICE TO BE RE-ORIENTATED AT EACH JOB TO BE CARRIED OUT

Applicable Tags

Root Causes- Personal Factor

Lack of Knowledge

Substandard Acts

Failure to observe basic safety rules

Follow Up

On	By	Follow Up	
26/Apr/2023	Nawin Khaware	Agree with preventive measures, Remain observant & ensure regular compliance with same.	

Before & After Pictures

Before	After
--------	-------