

# Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

# **Near Miss Details**

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Saint James LG Defect ID: 408

### **Defect Details**

The Hot water pot was found empty in officer crew mess room and messboy order to refill it, then he attempted to disconnet the equipment and bring it somewhere instead of find a bottle of water for the purpose.

Requisition Code:

Categories					
Primary :	Near Miss	Vessel Dept :	Deck		
Secondary :	Safe Working Procedures not Followed	Office Dept:	Safety		

# **Applicable Dates**

Date Raised: 24-May-2024 Date Completed: 07-Jun-2024

Other	Details	

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	07/Jun/2024

Potential to become a serious accident: Medium Recurrence: Low

# Causes

Lack of safety culture, knowledge to assess and identify hazards related with the task.

#### **Corrective Action**

Messboy was order to not handle the equipment while hot and still some liquid remaining inside. To find a bottle of water or any other suitable vessel for refilling the hot pot.

# **Preventive Action**

Discussion and analisis of the near miss during the next safety meeting / lesson learned & shared. Familiarization with the process of risk assessment.

# **CONTRIBUTING FACTORS**

# **Root Causes- Job Factor**

Inadequate Work Standards

# **Root Causes- Personal Factor**

Lack of Knowledge

Near Miss Details Printed On: 12-Jun-2024 1/2

Direct Causes- Unsafe Acts					
Improper Securing / Stowage					
Personal Factors					
Lack of Knowledge					
Substandard Acts					
Failure to observe basic safety rules					
Follow Up					
On	Ву	Follow Up			
Before & After Pictures					
Before			After		

Near Miss Details Printed On: 12-Jun-2024 2/2