



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 134

Defect Details

DURING RECEIVING OF PROVISIONS AT LOME ANCHORAGE WHEN LIFTING THE PROVISIONS ONBOARD ONE OF THE PROVISION SUPPLIER WORKER WAS STANDING UNDER THE ITEMS WHICH WAS BEEN LIFTED HE WAS IMMEDIATELY TOLD TO KEEP WELL CLEAR.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Training	Office Dept :	Safety

Applicable Dates

Date Raised : 25-Jan-2023

Date Completed : 01-Feb-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Feb/2023
Potential to become a serious accident : Medium			Recurrence : Medium		

Causes

LACK OF SAFETY AWARENESS

Corrective Action

IMMEDIATELY TOLD THE WORKER TO KEEP WELL CLEAR OF THE LIFTING ITEMS.

Preventive Action

BRIEF TOOLS BOX MEETING TO BE CARRIED OUT WITH SUPPLIES ON SAFETY WHEN LIFTING OR CARRY ITEMS ONBOARD.

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Lack of Knowledge

Substandard Acts

Failure to observe basic safety rules

Follow Up

On	By	Follow Up	
01/Feb/2023	Nawin Khaware	Concur with submitted preventive measures.	

Before & After Pictures**Before****After**