



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 80

Defect Details

During Routine Cleaning Oiler Was Blowing air on Workshop Machinery to Remove Chips and wooden Remains on Drill Machine, During the act he was without the Goggles, Officer Passing by Immediately stopped him, instructed to wear Goggles and Risk with flying metallic Chips. Also Instructed to be cautious in Future about PPE

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Improper PPE	Office Dept :	Safety

Applicable Dates

Date Raised : 25-Jun-2023	Date Completed : 25-Jun-2023
---------------------------	------------------------------

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : High			Recurrence : Low		

Causes

Failure to use proper PPE

Corrective Action

Activity stopped.

Preventive Action

The crew member retrained ref PPE.

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Improper Motivation

Direct Causes- Unsafe Acts

Failure to Use PPE Properly

Personal Factors

Lack of Knowledge

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After