l
-
MARITEC
TANKER MANAGEMENT

Maritec Tanker Management Private Limited

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel : Bahama I	Blue			Defect ID : 213					
Defect Details									
While getting off the accomodatin Stairs, Handrail was uprooted and nearly caused a 3rd Officer to fall. Luckily the incident was avoided due to proper maitaining 3 point contact on steps and ladder.									
Requisition Code :									
Categories									
Primary :	Near Miss		Vessel Dept :		Engine				
Secondary :	Other	Other		Dept :	General				
Applicable Dates									
Date Raised : 28-May-2024				Date Completed : 03-Jun-2024					
Other Details									
Priority :	Normal	QMS Elements Ref :		- SELECT -	Verified By :	Nawin Khaware			
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	07/Jun/2024			
Potential to become a serious accident : Medium				Recurrence : Low					
Causes									
Heavy weather, All supporting equipments to be maintained in order.									
Corrective Action									
Engineers Notified, immediately got the railing fixed.									
Preventive Action Regular accommodation rounds must be made by safety officer and Master to ensure all gears are maintained in good conditions.									
All crew members were advised to report immediately in case if such an important items are broken and not serving the purposes.									
CONTRIBUTING FACTORS									
Substandard Conditions									
Defective Ladders/ Stairs									
Ship Movement									
Follow Up									

On	Ву	Follow Up	
31/May/2024	Vitaliy Klimenko Staff Code - 10633 - MST	AWAITING OFFICE ACTION for this job has been changed to No	
31/May/2024	Vitaliy Klimenko Staff Code - 10633 - MST	AWAITING OFFICE ACTION for this job has been changed to Yes	
31/May/2024	Alister Pascaol Lobo Staff Code - 10582 - 3/OFF	Engineer notified and immediately got it firmly fixed back in place.	

Before & After Pictures

BeforeAfter