



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 84

Defect Details

During pre port arrival checks and deck round it was found that one of drip tray/save all plug is not closed properly.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Supervision / Leadership / Planning	Office Dept :	Safety

Applicable Dates

Date Raised : 29-Aug-2023

Date Completed : 29-Aug-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	06/Oct/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

LACK OF TRAINING.

Corrective Action

Pre port arrival checks as per checklist to be done.

Preventive Action

Port arrival checks as per checklist to be done and to be checked by duty officer while taking deck round.

CONTRIBUTING FACTORS

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Improper Motivation

Job Factors

Inadequate Work Standards

Personal Factors

Lack of Knowledge

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After