



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

#### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 265

#### Defect Details

Crew member found cleaning lube oil spare filter without wearing face shield.

Requisition Code :

#### Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Safe Working Procedures not Followed	Office Dept :	Safety

#### Applicable Dates

Date Raised : 30-Jan-2023

Date Completed : 01-Feb-2023

#### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Feb/2023
Potential to become a serious accident : Low			Recurrence : Low		

#### Causes

Carelessness

#### Corrective Action

Instructed to all crew member to use always proper PPE.

#### Preventive Action

Proper briefing carried out for all engine crew.

#### Applicable Tags

#### Root Causes- Job Factor

Inadequate Work Standards

#### Root Causes- Personal Factor

Lack of Knowledge

#### Direct Causes- Unsafe Acts

Failure to Follow Rules and Regulations

**Job Factors**

Inadequate Supervision

**Personal Factors**

Lack of Knowledge

**Substandard Acts**

Failure to observe basic safety rules

**Follow Up**

On	By	Follow Up	
01/Feb/2023	Nawin Khaware	Each crew member must take care of their personal safety and entire jobs must be supervised by senior officer to ensure jobs are completed safely.	

**Before & After Pictures**

Before	After
--------	-------