



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 265

Defect Details

Crew member found cleaning lube oil spare filter without wearing face shield.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Safe Working Procedures not Followed	Office Dept :	Safety

Applicable Dates

Date Raised : 30-Jan-2023

Date Completed : 01-Feb-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Feb/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Carelessness

Corrective Action

Instructed to all crew member to use always proper PPE.

Preventive Action

Proper briefing carried out for all engine crew.

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Personal Factor

Lack of Knowledge

Direct Causes- Unsafe Acts

Failure to Follow Rules and Regulations

Job Factors

Inadequate Supervision

Personal Factors

Lack of Knowledge

Substandard Acts

Failure to observe basic safety rules

Follow Up

On	By	Follow Up	
01/Feb/2023	Nawin Khaware	Each crew member must take care of their personal safety and entire jobs must be supervised by senior officer to ensure jobs are completed safely.	

Before & After Pictures

Before	After
--------	-------