

Before

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Saint James LG Defect ID: 324 NCR#: Is NCR?: No **Defect Details** Nitrogen Bottle for Mast riser firefighting system not located at mast riser. Same needs to be placed near mast riser. Requisition Code: Categories Primary: Cargo Inspector - Internal: Abhishek Gupta Vessel Dept: Deck Secondary: Miscellaneous Office Dept: Safety Inspector External: 01-Jun-2023 Inspection Date : **Applicable Dates** Date Completed: Date Raised: 01-Jun-2023 ETC: 15-Jun-2023 Other Details Priority: Normal Assigned By: Tech Suptd Verified By: Display in Daily Meeting? : No SFI: Verified On: Causes **Corrective Action Preventive Action** Applicable Tags Follow Up On Ву **Follow Up** 27/Jun/2023 Abhishek Gupta **Before & After Pictures**

Defect List Details Printed On: 17-Jul-2023 1/1

After