



# Maritec Tanker Management Private Limited

## Defect List Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River	Defect ID : 70	NCR # :	Is NCR ? : No
---------------------	----------------	---------	---------------

### Defect Details

DG BOX COOLER NO.1 (FWD/PORT) TUBES FOUND LEAKY). BOX COOLER ISOLATED. Requisition no. BTR-SOT-V240041 raised on 15 Jan 2024 for spares.

Requisition Code :

### Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Auxiliary Engines	Inspector External :		Office Dept :	Technical
		Inspection Date :			

### Applicable Dates

Date Raised : 13-Jan-2024	ETC : 30-Jun-2024	Date Completed :
---------------------------	-------------------	------------------

### Other Details

Priority : Urgent	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

### Causes

### Corrective Action

### Preventive Action

### CONTRIBUTING FACTORS

### Follow Up

On	By	Follow Up	
11/Jun/2024	Kamlesh Jalori	ETC has been changed from "30 Apr 2024" to "30 Jun 2024".	
10/Mar/2024	Ajay Kumar .   Staff Code - 10320 - C/E	EXPECTED COMPLETION DATE for this job has been changed from 29/Feb/2024 to 30/Apr/2024	
21/Jan/2024	Ajay Kumar .   Staff Code - 10320 - C/E	Vessel and Tech Supdt to ensure timely receipt of spares requested for cooler tube repairs. Vessel to plan/risk assessment at suitable draft/light ship conditions in consultation with Technical Supdt/Operations for removal of box cooler for repairs, viz pressure test and plug leaky tubes and ensure box cooler in operation ASAP.	

Before & After Pictures

Before

After