

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Demerara	Defect ID: 66	NCR # :	Is NCR ?: No
-------------------	---------------	---------	--------------

Defect Details

Curtain in welding / cutting area not fireproof

Requisition Code:

Categories					
Primary :	LSA/FFA	Inspector - Internal :	Fiacre Fonseca	Vessel Dept:	Engine
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept:	Technical
		Inspection Date :	14-Jan-2023		

Applicable Dates

Date Raised: 14-Jan-2023 ETC: 30-May-2023 Date Completed: 10-May-2023

Other Details

Priority: Normal Assigned By: Ops Suptd Verified By: Fiacre Fonseca

Display in Daily Meeting? : No SFI: Verified On : 19/May/2023

Causes

Corrective Action

Preventive Action

Applicable Tags

Descriptions

Others

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Root Causes- Management Factors

Inadequate Procedures / Checklists

Root Causes- Personal Factor

Inadequate Communication

Direct Causes- Unsafe Acts

Defect List Details Printed On: 21-Jun-2023 1/2

Failure to Follow Rules and Regulations

Job Factors

Inadequate Work Standards

Personal Factors

Lack of Knowledge

Follow Up

On	Ву	Follow Up	
19/May/2023	Fiacre Fonseca	ETC has been changed from "20 Apr 2023" to "30 May 2023".	
10/May/2023	Gelu Antin Staff Code - 10124 - MST	No certificates on board ,maker informed. Reply Attached.	Link1 Link2
27/Jan/2023	Fiacre Fonseca		

Before & After Pictures

Before After

Defect List Details Printed On: 21-Jun-2023 2/2