

## Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

## **Defect List Details**

**Bitu Atlantic** Defect ID : 127 NCR # : 4/2021 Is NCR ? : Yes Vessel: **Defect Details** Thermometer on loading manifold are not working Requisition Code : ATLC-DS-V210071 Categories Primary : Near Miss Inspector - Internal : Vessel Dept: Deck Technical Inadequate Inspector External : Office Dept: Maintenance / Secondary : Wear and Tear Inspection Date : **Applicable Dates** Date Raised : 19-Apr-2021 ETC: 26-Apr-2021 Date Completed : 23-Apr-2021 **Other Details** Priority : Urgent Verified By : Francis Timothy Assigned By : Vessel Monteiro Display in Daily Meeting? : No SFI: Verified On : 03/Jun/2021 Causes WEAR AND TEAR (NOT RELATED TO LACK OF MAINTENANCE) **Corrective Action** IMMEDIATELY THERMOMETER WAS REPLACED WITH ATHER ONE AND AFTER THAT LOADING WAS CONTINUED. **Preventive Action** CREW SHOULD KEEP PROPER MAINTENANCE OF MANIFOLD THERMOMETER AND ALLWAYS INSPECTED TEMPERATURE AND CONDITION. Applicable Tags Descriptions Others **Root Causes- Job Factor** Inadequate Purchasing **Root Causes- Management Factors** Stores / Spares Issue

Root Causes- Personal Factor				
Others				
Direct Causes- Unsafe Conditions				
Others				
Direct Causes- Unsafe Acts				
Failure to Follow Repair / Maintenance Instructions				
Job Factors				
Not Applicable				
Personal Factors				
Not Applicable				
Substandard Acts				
Other Unsafe Acts				
Substandard Conditions				
Defective Materials				
Follow Up				
On	Ву	Follow Up		
Before & After Pictures				
Before			After	