



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 158	NCR # :	Is NCR ? : No
----------------------	-----------------	---------	---------------

Defect Details

Tank monitoring system showed alarms for 1P COT: Low temp & Conv Calc Error and SLP Hart com Error

Requisition Code :

Categories

Primary :	Cargo Handling	Inspector - Internal :	Fiacre Fonseca	Vessel Dept :	Deck
Secondary :	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept :	Technical
		Inspection Date :	20-Jan-2023		

Applicable Dates

Date Raised : 20-Jan-2023	ETC : 20-Apr-2023	Date Completed : 10-May-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Ops Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Excessive Wear and Tear

Root Causes- Management Factors

Others

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Substandard Conditions

Electrical Fault (Other than Safety Devices)

Follow Up

On	By	Follow Up	
26/Jan/2023	Fiacre Fonseca		

Before & After Pictures

Before	After
--------	-------

	Ullage meter	Volume% %	Volume m³	Weight ton	Density t/m³ vac	Temp °C	Loadrate m³/h	Finis
E C1P	5.305	0.0	0.0	0.0	0.7406	-109.9		
A C1S	5.310	0.0	0.0	0.0	0.7406	28.5		
A C2P	5.306	0.0	0.0	0.0	0.8031	26.6		
A C2S	5.308	0.0	0.0	0.0	0.8031	28.9		
A C3P	5.314	0.0	0.0	0.0	0.7406	28.4		
A C3S	5.315	0.0	0.0	0.0	0.7406	28.0		
A C4P	5.312	0.0	0.0	0.0	0.8031	26.1		
A C4S	5.312	0.0	0.0	0.0	0.8031	26.8		
SLP	5.290	0.0	0.0	0.0	1.0250	27.5		
SLS	4.847	10.0	2.9	2.9	1.0250	29.9		
TotalAverage		0.2	2.9	2.9	0.8225	28.4	0.0	

