



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River	Defect ID : 20	NCR # :	Is NCR ? : No
---------------------	----------------	---------	---------------

Defect Details

Fused Lamp in the BT Room Non-Operational

Requisition Code :

Categories

Primary :	Others	Inspector - Internal :	Judas Fernandes	Vessel Dept :	Electrical
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Safety
		Inspection Date :	20-Mar-2023		

Applicable Dates

Date Raised : 20-Mar-2023	ETC : 19-Apr-2023	Date Completed : 14-Apr-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
09/May/2023	Mohamed Ajmal . Staff Code - 10310 - 4/E	THE FUSED LAMP IN THE BOW THRUSTER ROOM CHANGED WITH NEW ONE, PICS ATTACHED.	Link1 Link2 Link3
27/Mar/2023	Muddassar Jafri		

Before & After Pictures

Before	After
--------	-------



