

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra Defect ID : 96 NCR # : Is NCR ? : No

Defect Details

Paint store room door latched in open position, space prtected by CO2

Requisition Code:

Categories								
Primary :	Nav/Comm	Inspector - Internal:	Fiacre Fonseca	Vessel Dept:	Deck			
Secondary :	Navigation Equipment	Inspector External :		Office Dept:	Operations			
		Inspection Date :	25-Aug-2022					

Applicable Dates

Date Raised: 25-Aug-2022 ETC: 25-Sep-2022 Date Completed: 03-Sep-2022

Other Details

Priority : Urgent Assigned By : HSQE Suptd Verified By : Fiacre Fonseca

Display in Daily Meeting? : No SFI: Verified On : 28/Sep/2022

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Others

low	ш	-
 I LAAA	N-7	3.1

On	Ву	Follow Up	
29/Aug/2022	Muddassar Jafri		

Defect List Details Printed On: 17-Jul-2023 1/2

Before & After Pictures

Before

After



