

Maritec Tanker Management

Defect List Details

Vessel : Ken	ssel : Kensington LG Defect		D: 1 NCR # :		Is NCR ? : No		
Defect Details							
During test SW pump # 2 we found that , high vibration on entaired pump and smock coming from shaft seal when pump running. No pressure rise on SW line							
Requisition Code :							
Categories							
Primary :	E/R Machinery	Inspecto	or - Internal :		Vessel Dept :	Engine	
Secondary :	Miscellaneous	Inspector External :			Office Dept :	Technical	
		Inspection Date :					
Applicable Dates							
Date Raised : 27-May-2023			ETC : 03-Jun-2023		Date Complet	Date Completed : 05-Jun-2023	
Other Details							
Priority : Normal			Assigned By : Vessel Verifie		Verified By :	d By :	
Display in Daily Meeting? : No			SFI : Ve		Verified On :	Verified On :	
Causes							
Corrective Action							
Preventive Action							
Applicable Tags							
Root Causes- Job Factor							
Inadequate Maintenance							
Follow Up							
On	Ву		Follow Up				
Before & After Pictures							
Before				After			