



Maritec Tanker Management

Defect List Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Kensington LG	Defect ID : 1	NCR # :	Is NCR ? : No
------------------------	---------------	---------	---------------

Defect Details

During test SW pump # 2 we found that , high vibration on entaired pump and smock coming from shaft seal when pump running.
 No pressure rise on SW line

Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :			

Applicable Dates

Date Raised : 27-May-2023	ETC : 03-Jun-2023	Date Completed : 05-Jun-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------