

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Vessel: Bitu Atlantic	Defect ID: 158	NCR # :	Is NCR ?: No

Defect Details

Purifier area in E/R - Observed various leaks from the pump seals/joints of HFO fuel circulating pump. Oil soaked lagging could be sighted on the pipelines of associated area.

Requisition Code:

Categories					
Primary :	E/R Machinery	Inspector - Internal :	Nawin Khaware	Vessel Dept:	Engine
Secondary :	Valves & Filters	Inspector External :		Office Dept:	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised: 27-Sep-2021 ETC: 25-Oct-2021 Date Completed: 27-Dec-2021

Other Details		
Priority : Urgent	Assigned By: HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI:	Verified On:

Causes

leakage during purifier maintenance

Corrective Action

cleaned, painted

Preventive Action

to protect during purifier maintenance

Applicable Tags

Follow Up

On	Ву	Follow Up	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before	After
Belole	Aitei

Defect List Details Printed On: 04-Apr-2022 1/2







