



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 168	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Galley Supply vent - Mushroom type - Rubber gasket on closing flaps was found in poor condition which causes improper sealing of the vents. Requires renewal.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 30-Oct-2021	Date Completed : 29-Oct-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Follow Up

On	By	Follow Up	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before

After

