

Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Bitu	Bitu Atlantic Defect II		0 : 162		NCR # :		Is NCR ? : No	
Defect Details								
E/R workshop - visor kept on the top of grinding machine was not providing clear view as it had lots of scratches on it. Suggest to renew the visor.								
Requisition Code :								
Categories								
Primary :	Missing	Inspect	or - Internal:	Nav	win Khaware	Vessel Dept:	Engine	
Secondary :	Miscellaneous	s Inspector External				Office Dept:	Safety	
		Inspection Date :		27-3	Sep-2021			
Applicable Dates								
Date Raised : 27-Sep-2021			ETC: 30-Oct-2021			Date Completed : 30-Nov-2021		
Other Details								
Priority : Norn		Assigned By : HSQE Suptd			Verified By :			
Display in Daily Meeting? : No			SFI :			Verified On :		
Causes								
during using, generate span material								
Corrective Action								
renewed the protective visor Preventive Action								
periodicaly to be checked and renewed								
Applicable Tags								
Follow Up								
On	Ву		Follow Up					
05/Oct/2021	Nawin Kha	Nawin Khaware						
Before & After Pictures								
Before					After			