



## Maritec Tanker Management

### Defect List Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 161	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

#### Defect Details

During crew interview, it was brought to our notice that Fendering /De-fendering operation appears to be quite risky as same is carried out in heist or may be swing of fenders are not being controlled properly due improper handling of guiding ropes as it's . One of the valve spindle in the manifold area was broken due touching of fender which went uncontrolled. Vessel is advised to carry out the proper training of all the staff on fendering/de-fendering operation.

Requisition Code :

#### Categories

Primary :	Others	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Deck
Secondary :	Poor Performance	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

#### Applicable Dates

Date Raised : 27-Sep-2021	ETC : 25-Nov-2021	Date Completed : 28-Oct-2021
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Root Causes- Management Factors

Inadequate Training

#### Substandard Conditions

Ship Movement

#### Follow Up

On	By	Follow Up	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before



After

