



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 156	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Due change of fuel as vessel trading in EU waters, found oil sweating from M/E on the platform of emergency maneuvering area. Leaked oil on the machinery surface could pose a serious fire hazard hence as a prudent practice these oil leak must be cleaned and vessel should maintain all ship's machinery in leak proof condition.

Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :	Nawin Khaware	Vessel Dept :	Engine
Secondary :	Main Engines	Inspector External :		Office Dept :	Safety
		Inspection Date :	27-Sep-2021		

Applicable Dates

Date Raised : 27-Sep-2021	ETC : 25-Oct-2021	Date Completed : 13-Jan-2022
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
03/Jan/2022	Nawin Khaware	Submit the evidence for completion of work for our review.	
05/Oct/2021	Nawin Khaware		

Before & After Pictures

Before	After
--------	-------



