



Maritec Tanker Management

Defect List Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Bitu Express	Defect ID : 304	NCR # :	Is NCR ? : No
-----------------------	-----------------	---------	---------------

Defect Details

CCR Main Pannel Water Ballast Pump Delivery Valv in Shut Position, indication showing 30 percent Open

Requisition Code :

Categories

Primary :	Cargo Handling	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Cargo/ Ballast Machinery	Inspector External :		Office Dept :	Technical
		Inspection Date :	27-Jan-2023		

Applicable Dates

Date Raised : 28-Jan-2023	ETC : 28-Feb-2023	Date Completed : 02-Feb-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	By	Follow Up	
31/Jan/2023	Marin Panait Staff Code - 10017 - MST	Still under investigation. As the valve phisically is full close, vessel study the possibility to re-calibrate the indication.	Link1 Link2 Link3 Link4 Link5 Link6
28/Jan/2023	Marin Panait Staff Code - 10017 - MST	Under Investigation on board. Checked the delivery ballast valve, direct on the valv showing fully closed.	Link1 Link2

Before & After Pictures

Before



After









