



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga		
Report Date : 13-Apr-2023		
Location : engine room bottom platform		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : While opening the thermal boiler motor a crew member was using open end spanner size 19, crew member was stopped and asked to use ring side of the spanner.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	2/E was notified and same was discussed in next tool box meeting.
Action successful? :	Yes	
Report anonymous? :	Yes	2/E was notified and same was discussed in next tool box meeting.
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan, On sight training plays an integral role in improving work culture onboard the ship.		
Date Reviewed by DPA : 20-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		