

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Asphalt Teranga			
Report Date: 19-Apr-2023			
Location : DAKAR SENGENAL			
Unsafe Act Or Condition:			
Type : Unsafe Act			
Brief Details: AN A.B WORKING WITH FIRE WIRE WITHOUT WEARING HIS SAFETY GLOVES			
Was action taken at the time? :	Yes		
Was work stopped? :	No		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details: Use of PPE must be stressed upon all the time as PPE is the last line of defence to avoid having any personal injury.			
Date Reviewed by DPA : 26-Apr-2023			
Actions:			
Tick further Actions : No Further action required		Remarks :	Importance of PPE must be discussed during each safety meeting.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed: Yes			

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1