



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | | |
|---|----------------------------|-----------|---|
| Vessel : Asphalt Teranga | | | |
| Report Date : 19-Apr-2023 | | | |
| Location : DAKAR SENGENAL | | | |
| Unsafe Act Or Condition: | | | |
| Type : Unsafe Act | | | |
| Brief Details : AN A.B WORKING WITH FIRE WIRE WITHOUT WEARING HIS SAFETY GLOVES | | | |
| Was action taken at the time? : | Yes | | |
| Was work stopped? : | No | | |
| Officer notified? : | Yes | | |
| Action successful? : | Yes | | |
| Report anonymous? : | No | | |
| Any other comments or suggestions? Enter below: | | | |
| Brief Details : Use of PPE must be stressed upon all the time as PPE is the last line of defence to avoid having any personal injury. | | | |
| Date Reviewed by DPA : 26-Apr-2023 | | | |
| Actions : | | | |
| Tick further Actions : | No Further action required | Remarks : | Importance of PPE must be discussed during each safety meeting. |
| Link NC/Observation/Near Miss/ Risk Assessment : | | | |
| Followup Completed : Yes | | | |