

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Asphalt Teranga		
Report Date : 28-Jun-2023		
Location: MONROVIA LIBERIA		
Unsafe Act Or Condition:		
Type: Unsafe Condition		
Brief Details: DURING ROUTINE CHECKED IT WAS FOUND THAT LIMIT SWITCH OF DAVIT HOOK FOUND IN MALFUNCTION CONDITION DURING LUNCHING OF RESCUE BOAT IN FUTURE IT COULD LEAD TO FREE FALLING OF RESCUE BOAT		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details:		
Date Reviewed by DPA : N/A		
Actions:		