

Followup Completed: Yes

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bahama Blue Report Date: 21-May-2023 Location: MANIFOLD Unsafe Act Or Condition: Type: Unsafe Condition Brief Details: While using the crane during receiving provisions it was observed a crew member was standing directly under the suspended weight. Was action taken at the time? : Yes Duy officer observed the same and alerted the crew. He was made to clear the area andstay at safe distance. Was work stopped?: No Duy officer observed the same and alerted the crew. He was made to clear the area andstay at safe distance. Officer notified?: No Action successful?: Yes Report anonymous?: No Any other comments or suggestions? Enter below: Brief Details: Good observation, concur with action taken by duty officer. Date Reviewed by DPA: 25-May-2023 Actions: Tick further Actions: No Further action required Remarks: Discuss the hazards associated with standing underneath the suspended heavy objects. Link NC/Observation/Near Miss/ Risk Assessment:

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1