

## **Maritec Tanker Management**

## **Unsafe Act or Condition**

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bahama Blue				
Report Date : 21-May-2023				
Location: MANIFOLD				
Unsafe Act Or Condition:				
Type: Unsafe Condition				
Brief Details: While using the crane during receiving provisions it was observed a crew member was standing directly under the suspended weight.				
Was action taken at the time	e?: Yes	Duy officer observed the same and alerted the crew. He was made to clear the area andstay at safe distance.		
Was work stopped?:	No	Duy officer observed the same and alerted the crew. He was made to clear the area andstay at safe distance.		
Officer notified? :	No			
Action successful? :	Yes			
Report anonymous?:	No			
Any other comments or suggestions? Enter below:				
Brief Details: Good observation, concur with action taken by duty officer.				
Date Reviewed by DPA : 25-May-2023				
Actions:				
Tick further Actions:	No Further action required		Remarks :	Discuss the hazards associated with standing underneath the suspended heavy objects.
Link NC/Observation/Near Miss/ Risk Assessment :				
Followup Completed: Yes				

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1