

Followup Completed: Yes

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Vessel: Bahama Blue Report Date: 26-Apr-2023 Location: AFT Mooring Station Unsafe Act Or Condition: Type: Unsafe Condition Brief Details: During routine and safety round safety officer found out that mooring ropes in aft station are not secure and scattered. Was action taken at the time?: Yes Discuss to deck crew that agter departure all mooring ropes must be secure properly. Was work stopped?: No Discuss to deck crew that agter departure all mooring ropes must be secure properly. Officer notified?: No Action successful?: Yes Deck crew seure and arrange properly the mooring ropes. Report anonymous?: No Any other comments or suggestions? Enter below: Brief Details: Good observation & concur with action plan. Date Reviewed by DPA: 05-May-2023 Actions: Remarks: Tick further Actions: No Further action required Link NC/Observation/Near Miss/ Risk Assessment:

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1