



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra		
Report Date : 01-May-2023		
Location : Engine room bottom platform (bilge area)		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : Deep trays drain line found leaking and temporary leakage was arrested. Taken out drain pipe ,fabricated new line and put in place		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan, Pay good attention towards maintenance of pipelines in/around drip tray areas as leaks around manifold areas could pose a huge risk on oil pollution.		
Date Reviewed by DPA : 06-May-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		