

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Biskra		
Report Date: 10-Feb-2023		
Location: Engine Room		
Unsafe Act Or Condition:		
Type: Unsafe Condition		
Brief Details: On cargo pump no1, failed to restore safety guard after turning (manually)the motor/pump shaft, installed guard and secured		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Good observation, concur with vessel rectification plan.		
Date Reviewed by DPA : 11-Feb-2023		
Actions:		
Tick further Actions : No Further action required Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: Yes		

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1