

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Biskra			
Report Date: 10-Feb-2023			
Location: Engine Room			
Unsafe Act Or Condition:			
Type: Unsafe Condition			
Brief Details : On cargo pump no1, failed to restore safety guard after turning (manually)the motor/pump shaft, installed guard and secured			
Was action taken at the time? :	Yes		
Was work stopped? :	No		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details : Good observation, concur with vessel rectification plan.			
Date Reviewed by DPA : 11-Feb-2023			
Actions:			
Tick further Actions : No Further action required Remarks :			
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed: Yes			

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1