

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Biskra		
Report Date : 14-May-2023		
Location: MAIN DECK		
Unsafe Act Or Condition:		
Type: Unsafe Act		
Brief Details: ON 14.05.2023 AT LOME ANCHORAGE, WHILE RIGGING UP FENDERS FOR BERTHING IN MINERAL PIER, A CREW MEMBER FOUND UNDERNEATH THE FENDER, ON THE SAME TIME DUTY OFFICER NOTICED AND TOLD HIM TO STAY OUT OF THE RANGE OF LIFTING OBJECT, AFTER THE JOB HAS COMPLETED SUCCESFULY.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details: Good observation, concur with action plan.		
Date Reviewed by DPA : 18-May-2023		
Actions:		
Tick further Actions : No Further action required Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: Yes		

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1