

## **Maritec Tanker Management**

## **Unsafe Act or Condition**

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Biskra		
Report Date: 15-Jan-2023		
Location: E/R WORKSHOP		
Unsafe Act Or Condition:		
Type: Unsafe Act		
Brief Details: Found Engine fitter using electical grinding machine without protecting guard, stoped the work and asked the fitter to fix the guard, same fitted and carried work		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Good observation, concur with your action plan.		
Date Reviewed by DPA : 18-Jan-2023		
Actions:		
Tick further Actions : No Further action required Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: No		

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1