



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 05-Feb-2023		
Location : Suprastructure EGCS		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : The external doors from EGCS room found un secured properly according to vessel hardening plan for HRA MDAT GoG West Africa		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details : All doors must be kept closed from inside while transiting in HRAs.		
Date Reviewed by DPA : 09-Feb-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		