



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 15-Mar-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : Fire Extinguisher taken out from its position for bunkering operation was not restored back in its position after completion of operation.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	No	Observed by Officer
Action successful? :	Yes	
Report anonymous? :	Yes	Observed by Officer
Any other comments or suggestions? Enter below:		
Brief Details : All LSA/FFA items must be stowed back in position after the drill or maintenance. These items must be maintained in the state of readiness all the time.		
Date Reviewed by DPA : 22-Mar-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks : Pls discuss during QHSE meeting regarding importance for keeping LSA/FFA items in the states of readiness all the time.
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		