

Tick further Actions:

Link NC/Observation/Near Miss/ Risk Assessment :

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A

Issue: N/A Revision: N/A Rev Date: N/A

Vessel: Bitu Atlantic Report Date: 18-Apr-2023 Location: ENGINE ROOM WORKSHOP Unsafe Act Or Condition: Type: Unsafe Act Brief Details: Obesrved tray remain with diesel oil in workshop, after cleaning filters. Was action taken at the time?: Yes Tray removed immedialety. Was work stopped?: No Tray removed immedialety. Officer notified?: Yes Explain about procedure. Action successful? : Yes Report anonymous?: Yes Explain about procedure. Any other comments or suggestions? Enter below: Brief Details: Open oil container poses a fire hazard hence same must be kept inside closed container and away from the source of heat/ignition. Date Reviewed by DPA: 25-Apr-2023 Actions:

Followup Completed: Yes

Remarks:

No Further action required

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1