

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Express							
Report Date: 04-Jan-2023							
Location: Main deck							
Unsafe Act Or Condition:							
Type: Unsafe Condition							
Brief Details: During routine inspection on deck, 3rd officer found one fire hose incorrect position, the fire hose was out from the fire box.							
Was action taken at the time? :	Yes						
Was work stopped? :	No						
Officer notified?:	Yes						
Action successful? :	Yes						
Report anonymous? :	No						
Any other comments or suggestions? Enter below:							
Brief Details: All safety gears must be stowed back in proper location so that during emergency, same could be used without any issues.							
Date Reviewed by DPA : 12-Jan-2023							
Actions:							
Tick further Actions : No Further action required Remarks :							
Link NC/Observation/Near Miss/ Risk Assessment :							
Followup Completed: Yes							

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1