

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Express			
Report Date: 10-Jan-2023			
Location: Bosun Store			
Unsafe Act Or Condition:			
Type: Unsafe Condition			
Brief Details: During weekly inspection was observed that indicator for Bosun Store Watertight door (Close/Open) out of order.			
Was action taken at the time? :	Yes		
Was work stopped? :	No		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details: Proper maintenance of all doors must be carried out as per PMS, ensure all store doors are opening/closing properly.			
Date Reviewed by DPA : 13-Jan-2023			
Actions :			
Tick further Actions: No Further action required		Remarks :	Check all W/T doors and ensure they are opening/closing properly.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed: Yes			

Unsafe Act or Condition Printed On: 27-Sep-2023 1/1