



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Express			
Report Date : 10-Jan-2023			
Location : Bosun Store			
Unsafe Act Or Condition:			
Type : Unsafe Condition			
Brief Details : During weekly inspection was observed that indicator for Bosun Store Watertight door (Close/Open) out of order.			
Was action taken at the time? :	Yes		
Was work stopped? :	No		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details : Proper maintenance of all doors must be carried out as per PMS, ensure all store doors are opening/closing properly.			
Date Reviewed by DPA : 13-Jan-2023			
Actions :			
Tick further Actions :	No Further action required	Remarks :	Check all W/T doors and ensure they are opening/closing properly.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			