



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Express		
Report Date : 12-Jan-2023		
Location : Paint Locker		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : During routine rounds on deck Safety Officer , noticed strong odor, later on he find open bucket of thinner near entrance in Paint locker.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : All paints/thinners must be stored in covered drums, open thinner may poses a risk of fire hazards.		
Date Reviewed by DPA : 19-Jan-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		