

Unsafe Act or Condition

Vessel : Bitu Express			
Report Date: 21-Jan-2023			
Location : E/R			
Unsafe Act Or Condition:			
Type : Unsafe Condition			
Brief Details : During safety round were found that one fire extinguisher was not secured properly In the floor of Engine Room.			
Was action taken at the time? :	Yes		
Was work stopped? :	Yes		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous?:	Yes		
Any other comments or suggestions? Enter below:			
Brief Details : Good observation, concur with action plan by putting back the extinguisher in place.			
Date Reviewed by DPA : 27-Jan-2023			
Actions :			
Tick further Actions : No I	No Further action required		Importance of securing to be discussed with all crew.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			