



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Express		
Report Date : 26-Jan-2023		
Location : MAIN DECK		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During safety, security fire round were found spots of grease near the forward mooring windless. Safety issue and lack of environmental protection awareness.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : All deck area must be maintained in clean condition at all times and oil/grease must be cleaned off immediately in case same is found fallen anywhere on deck.		
Date Reviewed by DPA : 27-Jan-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		